



ADHESIVE SAFETY PRECAUTIONS

The handling of hot melt adhesives in their molten state should be undertaken with great care abiding by all safety precautions:

To protect the operator, observe the following rules:

- 💡 *DO: Wear appropriate clothing at all times.*
- 💡 *DO: Wear eye protection when necessary*
- 💡 *DO: Provide adequate ventilation to remove any hot melt fumes or vapors generated.*
- 💡 *DON'T: Allow adhesive or padding pot to come in contact with any part of your body.*

To protect the hot melt, observe the following rules:

- 👉 *DO: Rotate stock using oldest material first. **Brackett** hot melt adhesives have an estimated shelf life of about 12 months.*
- 👉 *DO: Store adhesives at room temperature.*
- 👉 *DO: Keep containers, premelters and glue pots covered to avoid contamination.*
- 👉 *DON'T: Mix with other adhesives without consulting the manufacturer.*

This information pertains to all the Brackett adhesives in general.

Each individual product has its own “spec” sheet available by mail, e-mail or online.